

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans
 Run date
 22-Nov-14

 Time
 8:15 AM

04-0120F4

04-SF-80-13.2/13.9

Self-Anchored

Suspension Bridge

Dispute

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 600 Const Calendar Day: Inspector Name: Feather, Bernard

Date: 28-Jul-2014 Monday
Title: Transportation Engineer

Inspection Type: Intermittent

Shift Hours: 08:00 am 10:00 pm **Break:** 05:00 **Over Time:** 01:00

784

Federal ID: Location:

Reviewer: Shedd, Bill

Approved Date:

Status: Submit

Weather

Temperature 7 AM

12 PM

4PM

Precipitation

Condition Clear, warm

Working Day 🗸 If no, explain:

Diary:

General Comments

Bill Casey staff meeting 0800-0900. Track progress of FWS tightening of CA and DW valves along the bike path. Track progress of CCC painting of the CCO 187 installed pipe supports between PP 126 and Hinge AW/AE. Misc MEP paperwork and write diaries. Ken Chan provided the overnight inspection for CT.

 04-0120F4
 Bid Item:
 126
 0-000-000.126

 F.W. SPENCER AND SON, INC

 Labor

RT Hrs OT Hrs DT Hrs Total Remarks Name Dispute Trade Class F.W. SPENCER AND SON, INC Contractor: NARCISO BIAGI Plumber/Pipefitter JNM 5.00 0.00 0.00 5.00 TOM COLOMBO Plumber/Pipefitter FOR 2.50 0.00 0.00 2.50

COMPRESS AIR (4 NPS)

Diary:

Bike Path Piping

126 0-000-000.126

The FWS crew, including Josh Johnson and Tim Esquivel, went on shift at Pier 7 at 2200 on July 28, 2014. The closure of the #5 lane of the EB bridge was set up at 2300, and the crew established themselves in the closure at 2325. The crew spent the shift tightening the valves on the CA and DW utility stations along the bike path, identified with the soap test during the pressure testing of those lines, and as noted on the Mechanical Punchlist. The crew also reinstalled the U-bolts at the PS-7 located at PP 68. The painters removed these u-bolts when priming and painting the pipe and pipe supports.

The crew used the 70 amp welding machine as a generator in performance of this work

The crew left the bridge at 0411 on July 29, 2014 and went off shift at 0500.

Ken Chan provided the overnight inspection for CT. His diary is as follows:

Crew started the work at 11:25pm at SAS, the work was to apply threads and pipe sealing to 2 valves alongside the bike path pedestal, a total of 7 air valves were repaired so far; At panel pt. 68, installing U-bolts on both the 2.5" and 4" pipes, 2 bolts on each pipe. Crew was off the bridge by 4:10am.

CCO-187 Bid Item: 001 0-MSI-EFA.187 MEP/Structural Interferences
CERTIFIED COATINGS COMPANY

Labor

ddrRptbyBidltem

Page 1 of 2

Daily Diary Report by Bid Item

Inspector Name Feather, Bernard Job Name: 04-0120F4 Diary #: 600 Date: 28-Jul-2014 Monday Trade Class Name RT Hrs OT Hrs DT Hrs Total Remarks Dispute Contractor: CERTIFIED COATINGS COMPANY Painter JNM **GENIER VALDES** 8.00 0.00 0.00 8.00 Painter APP Victor Ruiz 8.00 0.00 0.00 8.00 Dispute Diary: **CB 19 Expansion Loop** 001 0-MSI-EFA.187 Vitor Ruiz and Genier Valdes completed the painted of the CCO 187 added pipe supports in the expansion loop at PP 126 and to Hinge AW/AE along the IB barriers. CCO-354 Bid Item: 001 0-FWS-ELS.354 CIC - Mechanical Impacts - F.W. Spencer F.W. SPENCER AND SON, INC Labor Name RT Hrs OT Hrs DT Hrs Total Remarks Dispute Trade Class Contractor: F.W. SPENCER AND SON, INC Plumber/Pipefitter JNM NARCISO BIAGI 3.00 0.00 0.00 3.00 Plumber/Pipefitter FOR TOM COLOMBO 1.50 0.00 0.00 1.50 Dispute Diary: 001 0-FWS-ELS.354 **Mechanical Change of** The FWS crew, including Josh Johnson and Tim Esquivel, spent 3 hours to mobilize to and from the bridge which will be paid under CCO 354. In addition, the pipefitter's union agreement gives them a 12% hourly shift differential and 8th hour of pay for 7 hours of work for working at night, which is also compensable under CCO 354. In addition to the equipment used in performance of the work, the crew used a towed port-a-potty and a light tower which will be paid via monthly invoice under CCO 354. The three crew trucks used will be paid per the equipment rental rate under CCO 354.

